

CORNER HISTORY: 1883 Marion County Atlas pg. 5 by Laughlin reflected a point called 'p'. This is a double corner with 92.25' between the two section corners. Reference dated 7-1933 by Burres called cut stones found. Reference dated 10-5-48 by Burres called the same. Reference dated 10-5-63 called brass plug found in concrete. Reference dated 10-1-03 found Maurer capped rebar by Wilcoxen found per older ties and GPS coordinates. Reference dated 10-2-07 by Wilcoxen called set Harrison marker per State Job by Reith Riley and a Maurer capped rebar was found 24" down. Set Harrison over capped rebar as per ties.

REF.	DISTANCE	DESCRIPTION
1.	44.40'	Cut 'x' SF bolt of aluminum pole base
2.	49.86	Mag nail w/bw S PwP#55-692A 50"up
3.	14.50'	Mag nail w/bw NF PwP#54-692A 48"up
4.	121.17'	Mag nail w/bw F PwP#183-692A 24" up